

# Extra Heavy Duty One Coat System for Aluminum

Aluminum Must Be Washed With Chem - Etch to Prepare Surface

Thickness Shown In Dry Mils

52-7000 Polyaspartic Urethane Hybrid Direct To Metal

10-12

